

PHILLIPS 66 CO -- 49560 SUPER HD II MOTOR OIL ALL GRADES

=====

MSDS Safety Information

=====

FSC: 9150

MSDS Date: 07/31/1996

MSDS Num: CGHJD

LIIN: 00F032193

Product ID: 49560 SUPER HD II MOTOR OIL ALL GRADES

MFN: 02

Responsible Party

Cage: GO225

Name: PHILLIPS 66 CO

Address: 699 ADAMS BLDG 411 KEELER

City: BARTLESVILLE OK 74004-5000

Info Phone Number: 918-661-8327/918-661-8327

Emergency Phone Number: 918-661-3865/918-661-8327

Review Ind: Y

Published: Y

=====

Preparer Co. when other than Responsible Party Co.

=====

Cage: GO225

Assigned Ind: Y

Name: PHILLIPS 66 CO

Address: 699 ADAMS BLDG

City: BARTLESVILLE OK 74004

=====

Contractor Summary

=====

Cage: 5W135

Name: GLENN OIL COMPANY INC

Address: UNKNOWN

Box: UNKNOW

City: UNKNOWN NK 00000

Phone: UNKNOWN

Cage: GO225

Name: PHILLIPS 66 CO

Address: 699 ADAMS BLDG

City: BARTLESVILLE OK 74004

Phone: 918-661-8327

Cage: 6Y142

Name: PHILLIPS 66 COMPANY(DIVISION OF PHILLIPS PETROLEUM CO)

Address: 699 ADAMS BLDG 411 KEELER ST

City: BARTLESVILLE OK 74004

Phone: 918-661-8327

=====

Ingredients

=====  
Name: HYDROCARBON MIXTURE  
=====

Health Hazards Data  
=====

Route Of Entry Inds - Inhalation: YES

Skin: NO

Ingestion: NO

Carcinogenicity Inds - NTP: NO

IARC: NO

OSHA: NO

Effects of Exposure: EYES: MILD IRRITANT. SKIN: MILD IRRITANT

W/PROLONGED/REPEATED CONTACT. PRESSURIZED INJECTION OF PRODUCT UNDER THE SKIN CAN LEAD TO SERIOUSLY INFLAMMED TISSUE. IF LEFT UNTREATED, INJURY CAN BE DANEROUS . PROLONGED/REPEATED EXPOSURE TO OIL MIST POSES A RISK OF PULMONARY DISEASE/LUNG INFLAMMATION.

Explanation Of Carcinogenicity: NONE

Signs And Symptions Of Overexposure: IRRITATION, INFLAMMATION

First Aid: EYES: FLUSH W/RUNNING WATER. SKIN: WASH W/SOAP & WATER.

INHALATION: REMOVE FROM EXPOSURE. OBTAIN MEDICAL ATTENTION IN ALL CASES. NOTE TO PHYSICIAN: FOR INJECTION INJURIES, IMMEDIATE MEDICAL TREATMENT IS REQUIRED. PHYSICIANS MAY CALL EMERGENCY NUMBER (918) 661-8118.

=====  
Handling and Disposal  
=====

Spill Release Procedures: WEAR PROTECTIVE EQUIPMENT/GARMENTS IF EXPOSURE CONDITIONS WARRANT. SHUT OFF SOURCE, IF POSSIBLE & CONTAIN RELEASE. KEEP OUT OF WATER SOURCES & SEWERS. ABSORB IN DRY, INERT MATERIAL. TRANSFER TO DISPOSAL DRUMS.

Waste Disposal Methods: INCINERATE/MANAGE AT A PERMITTED WASTE MANAGEMENT FACILITY/DISPOSE OF IAW/LOCAL, STATE & FEDERAL REGULATIONS.

Handling And Storage Precautions: USE W/ADEQUATE VENTILATION. WEAR PROTECTIVE EQUIPMENT/GARMENTS IF EXPOSURE CONDITIONS WARRANT. STORE IN CLOSED CONTAINERS IN WELL VENTILATED AREA.

Other Precautions: AVOID CONTACT W/EYES, SKIN/CLOTHING. AVOID BREATHING VAPORS, FUME/DUST.

=====  
Fire and Explosion Hazard Information  
=====

Flash Point Method: COC

Flash Point Text: >365F

Extinguishing Media: DRY CHEMICAL, FOAM/CO2

Fire Fighting Procedures: EVACUATE AREA. SHUT OFF SOURCE. USE NIOSH/MSHA APPROVED SCBA & OTHER PROTECTIVE EQUIPMENT/GARMENTS. WATER FOG/SPRAY MAY BE USED TO COOL CONTAINERS & EQUIPME